







**Identificación de los Problemas/aspectos del Caso #,
Familia “Juarez”, Las Lomas, Rio Grande City**

Photos	Problema encountered	Proposed solution	Whom – skill level etc
	<p>New double lazed windows installed and frames around them rotted in rains. Removed. This window is also installed upside down</p>		
	<p>Not a problem, but two sets of steps rather than a ramp.</p>	<p>Instal a ramp when necessary</p>	
	<p>Roof leaking</p>	<p>Rebitumnize and then reseal; and then radiante barrier again.</p>	
	<p>Dilapidated sides; botched window installation; inadequate skirt around trailer – animals get under and infestation</p>	<p>Replace the skirt</p>	
	<p>Corner join poorly articulated: 5” gap and temporary covering inadequate. No insulation between two units. Blind Windows between the two units</p>	<p>Replace and ensure that under deck is also skirted to avoid animals getting in</p>	
	<p>No door to Jose Luis’ room. Creates problems and inefficiency of AC in his room.</p>		